

Legend


Sanitary Sewer Condition

Poor

Fair

Average

Good



IMAGERY SOURCE: 2008 DRAPE IMAGERY

PROJECT:

TOWNSHIP OF BONNECHERE VALLEY ASSET MANAGEMENT PLAN  
VILLAGE OF EGANVILLE, BONNECHERE VALLEY, ONTARIO

DRAWING:

SANITARY SEWER CONDITION RATING

JR

J.L.Richards

ENGINEERS · ARCHITECTS · PLANNERS

www.jlrichards.ca

This drawing is copyright protected and may not be reproduced or used for purposes other than execution of the described work without the express written consent of J.L. Richards & Associates Limited.

DESIGN: T.O'B.

DRAWN: K.T.K.

CHECKED:

JLR NO: 21981-21

DRAWING NO.: 5

File Location: P:\21000\21981-21 Eganville AMP\JLR DWG\Plan\Pipe\_Network\21981-21 FIG 5 SAN COND.mxd

Plot Date: Wednesday, August 07, 2013 8:46:19 AM